April 18, 2016

United States Environmental Protection Agency Air Compliance Branch 290 Broadway, 21<sup>st</sup> Floor New York, NY 10007-1866

Attn: NESHAP COORDINATOR

Re: NEWARK INTERNATIONAL AIRPORT – BUILDING # 105,

**ROOF REPLACEMENT** 

OPERATOR PROJECT#: 924.175A

Dear Madam/Sir:

Our courtesy notification for the asbestos abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 201-595-4881.

Sincerely,

Uday Mehta, Manager

Environmental field Operations

Construction Management Division

Cc:

Project File (EPA-2445)

Non-RACM Notification File

UM/fl

Operator Project #:	924.175A <b>Postma</b>	rk:	Date Received: 04/18/2016 Notification #: EPA-24		2445		
I. Type of Notificati	I. Type of Notification (O=Original R=Revised C=Canceled) O						
II. Facility Informati	on (Identify owner, removal cont	ractor, and other op	erator)				
Owner Name:	THE PORT AUTHORITY OF NY	& NJ					
Address:	241 ERIE ST. ROOM 236						
City:	JERSEY CITY State: NJ Zip: 07310						
Contact:	R. CAMPIONE, FACILITY SUPERVISOR, ASBESTOS OPS Telephone: 973-622-0800						
Removal Contracto	Removal Contractor: B&N&K RESTORATION CO. INC						
Address:	223 RANDOLPH AVENUE						
City:	CLIFTON State: NJ Zi			<b>Zip:</b> 07011			
Contact:	ALEKOANDER KURIERA			973-47	8-4681		
Other operator:	N/A						7.0
Address:				and the second s			
City:		S	tate:		Zip:		
Contact:					Telephone:		
III. Type of Operat	ion (D=Demo O=Ordered Der	no R=Renovatio	n E=Emergency	) R			
	esent? (Yes/No) YES			1			
	tion (include building name,	number. floor. an	d /or room numl	ber):			
	: NEWARK LBERTY INTERNATION						
Address:	NEWARK LIBERTY INTERNATION	ONAL AIRPORT					
City:	NEWARK						
Site Location:	County. LooLA						
Building Size:	ATTACK AND ATTACK						
Present Use:	TOLL PLAZA	# of Floors:2 Age in Years:50+  Prior Use: TOLL PLAZA					
	luding Analytical Method, If A	ppropriate, Used					
Control Contro	BULK SAMPLING UTILIZING PLM METHODS						
VII. Approximate Am	nount of Asbestos, Including:	Non-RACM	RACM to Be Removed	Nonfriable Asbestos Materials			
1. Regulated A	ACM to be Removed			Not To B	e Removed	Indi	Indicate
2. Category I / 3. Category II	ACM Not Removed ACM Not Removed	To Be Removed		Cat I	Cat II	Measurement	
Pipes			***************************************			Lnft:	0
Surface Area TAR PA	PER, ROOF FLASHING	465				Sqft:	465
Vol RACM Off Facility						Cuft:	0
VIII. Scheduled Dates Asbestos Removal Start: 04/18/2016 Complete: 06/30/2016							
IX. Scheduled Dat	es Demo\Renovation		Start:		Complete:		

X. Description	of Planned Demolition or Renovation Work, and Met	hod(s) to Be Used:	848 41 77		
			11 100 012		
At the Dem	n of Work Practices and Engineering Controls to Be olition And Renovation Site: EXTERIOR REMOVAL WITH NO VISIABLE EMMISIONS	Used to Prevent Emissions Of As	sbestos		
XII. Waste Trai	nsporter #1				
Name:	TWO BROTHERS CONTRACTING				
Address:	250 RUTHERFORD BOULEVARD				
City:	CLIFTON	State: NJ	Zip: 07014		
Contact:	SAL MLADENOVIC		Telephone: 973-956-8700		
Waste Tran	sporter #2				
Name:	N/A				
Address:					
City:		State:	Zip:		
Contact:			Telephone:		
XIII. Waste Dis	posal Site				
Name:	GROWS NORTH LANDFILL	<b>Y</b>			
Location:	1000 NEW FORD MILL ROAD				
City:	MOORISVILLE	State: PA	Zip: 19067		
Telephone	::330-866-3435				
XIV. If Demolit	on Ordered By a Government Agency, Please Identif	y the Agency Below			
Name:		Title:			
Authority:					
Date of Or	Date of Order: Date Ordered To Begin:				
XV. For Emergency Renovations					
Date and Ho	ur of Emergency: N/A				
	of Sudden or Unexpected Event:		1		
N/A	, , , , , , , , , , , , , , , , , , , ,				
Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:  N/A					
XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder:  IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS					
XVII. I Certify The Demolition for inspect	nat an Individual Trained in the Provisions of This Regulation or Renovation And Evidence That the Required Training Hition	on (40 CFR Part 61, Subpart M) Will B las Been Accomplished by This Pers	on Will Be Available		
XVIII. I Cerify Th	at the Above Information Is Correct.	(Signature of Owner/Operator)	04-18-16 (Date)		

April 18, 2016

United States Environmental Protection Agency Air Compliance Branch 290 Broadway, 21<sup>st</sup> Floor New York, NY 10007-1866

Attn: NESHAP COORDINATOR

Re: JOHN F. KENNEDY INTERNATIONAL AIRPORT – BUILDING # 14,

THIRD FLOOR, ACDTV ROOM, VAT ABATEMENT

OPERATOR PROJECT#: 1048.05

Dear Madam/Sir:

Our courtesy notification for the asbestos abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 201-595-4881.

Sincerely,

Uday Mehta, Manager

Environmental field Operations

Construction Management Division

Cc:

Project File (EPA-2443)

**RACM Notification File** 

UM/fl

Operator Project #: 1048.05	Postmark:		Date Received: 04/18/2016 Notification #: EPA-2443			#; EPA-2443
I. Type of Notification (O=Original F						
II. Facility Information (Identify owner	r, removal contractor, a	and other o	perator)			
Owner Name: THE PORT AUT	HORITY OF NY & NJ			-		
Address: 241 ERIE ST. R	OOM 236					
City: JERSEY CITY	JERSEY CITY State: NJ Zip: 07310					
Contact: N. CLAYTON, F						
Removal Contractor: NEW YORK ENVIRONMENTAL SERVICES						
Address: 368 RICHARDS	ON STREET					
City: BROOKLYN			State: NY		<b>Zip:</b> 11222	
Contact: RALPH SEVERI	NO				Telephone:	718-302-3500
Other operator: N/A					•	
Address:						
City:		S	state:		Zip:	
Contact:					Telephone:	
III. Type of Operation (D=Demo C	=Ordered Demo R=I	Renovatio	n E=Emergency	v) R		
IV. Is Asbestos Present? (Yes/No)				1		
V. Facility Description (include but		r. floor. an	d /or room num	ber):		
Building Name: JOHN F. KENNE			and to the first	2017.		
Address: JOHN F. KENNE	DY INTERNATIONAL A	IRPORT				
City: JAMAICA						
Site Location: BUILDING # 14	State. W County: QUEENS					
Building Size: 547,000		#	of Floors: 3RD		Ago in Vocas	10+
Present Use: OFFICES		# of Floors: 3RD Age in Years: 40+  Prior Use: OFFICES				
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material:						
BULK SAMPLING WITH TEM ANALYSIS.						
VII. Approximate Amount of Asbestos	, Including:	Non-RACM To Be Removed	RACM to Be Removed	Nonfriable Asbestos Materials		
<ol> <li>Regulated ACM to be Remove</li> <li>Category I ACM Not Removed</li> </ol>				Not To B	e Removed	Indicate Measurement
Category II ACM Not Removed     Action of the state				Cat I	Cat II	
Pipes						Lnft: 0
Surface Area VAT AND MASTIC			550			Sqft: 550
Vol RACM Off Facility Component						Cuft: 0
VIII. Scheduled Dates Asbestos Removal Start: 5/02/2016 Complete: 11/30/2016						
IX. Scheduled Dates Demo\Renov	ation		Start:		Complete:	

X. Description REMOVAL US	n of Planned Demolition or Renovation Work, and SING WET METHODS WITH SURFACE AND ISOLATION	Method(s) to Be Used: BARRIERS	
At the Dem	on of Work Practices and Engineering Controls to molition And Renovation Site: ROLUSING METHODS, ISOLATION AND SURFACE BARF		
MACHINES,V	ACUUMS WITH HEPA FILTERS AND WET REMOVAL AS	PER NEW YORK STATE IN	NDUSTRIAL CODE 56
XII. Waste Tra	nsporter #1		
Name:	ATC		a-
Address:	2 MORICHES MIDDLE ISLAND ROAD		
City:	SHIRLEY	State: NY	<b>Zip:</b> 11967
Contact:	GARY CRETTY		Telephone: 631-924-5050
Waste Tran	nsporter #2		
Name:	N/A		1
Address:			
City:		State:	Zip:
Contact:			Telephone:
XIII. Waste Dis	posal Site		
Name:	MINERVA ENTERPRISES		
Location:	8955 MINERVA ROAD		
City:	WAYNESBURG	State: OH	Zip: 44688
	e:330-866-3435		•
XIV. If Demolit	tion Ordered By a Government Agency, Please Ide	entify the Agency Below	
Name:		Title:	2.
Authority:			
Date of Or	rder:	Date (	Ordered To Begin:
XV. For Emerg	gency Renovations		Mariou 10 Dog
	our of Emergency: N/A		
	of Sudden or Unexpected Event:		
N/A			
Explanation o	of How the Event Caused Unsafe Conditions or Would C	ause Equipment Damage o	r an Unreasonable Financial Burden:
Asbestos IMMEDIATE IS WIPING ALL A	ons of Procedures to Be Followed in the Event That Material Becomes Crumbled, Pulverized or Reduction OF THE AREA AND ADEQUATE WETTING OF AFFECTED AREAS	iced to Powder: F ASBESTOS MATERIAL FO	DLLOWED BY HEPA VACUUMING AND WET
XVII. I Certify Th Demolition for inspect	hat an Individual Trained in the Provisions of This Regul n or Renovation And Evidence That the Required Trainin tion	lation (40 CFR Part 61, Subj ng Has Been Accomplished (Signature of Ov	This Person Will Be Available
XVIII. I Cerify Tha	at the Above Information Is Correct.	Signature of Ow	vner/Operator) OH-/6-/8